

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER **3** P. **127**

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY 8	T. 2 N. R. 1 E.	D-5
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E.	
4. LOT NO. RECORDED PLAT		
5. PRIVATE CLAIMS		

FILED

MAY 21 1 09 PM '74

REGISTER OF DEEDS

Charles E. Garlock
INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Charles E. Garlock do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 9-21 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

B. Description of corner evidence found and or method applied in restoring or re-establishing corner:

Set 1/2" Iron Rod

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Witnesses to S 1/4 cor. Section 8 T2N-R1E Ingham Township.

N 0° 00' 20" E 33.00' fd. Iron
South 33.00' $\frac{1}{2}$ cor. post & fence line South.

SIGNED BY *Charles E. Garlock* DATE May 18, 1974

SURVEYOR'S MICHIGAN REGISTRATION NO. 14762

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. _____

707

Form No. ML 25736
DOWLEBY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, APR. 26, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 480

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	1 2N 2 R 1E 1 W	E-5
2. PROPERTY CONTROL- ING IN SECTION 8	1 2N 2 R 1E 1 W	9, 16
3. MISCELLANEOUS PROPERTY IN SECTION	1 2N 2 R 1E 1 W	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

FILED

NOV 25 9 34 AM '75

REGISTER OF DEEDS
Ernest M. Lewis
 INGHAM COUNTY, MICH.
 REGISTER OF DEEDS STAMP AND
 FILING NUMBER

I, **George M. Young** do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram) were, in a field survey on **9-22 1975**, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current annual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on **10 1975**, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

E-5 Unknown
 9 Unknown
 16 Unknown



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-5 Found "PK" Nail in Bridge Deck
 9 Found 1/2" re-rod
 16 Set 1/2" re-rod According to government regulations

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-5 Found "PK" Nail-South Edge bridge guardrail N80°W 14.07'
 North Edge bridge guardrail S45°W 21.84'
 North Edge bridge guardrail S50°E 21.59'
 South Edge bridge guardrail N80°E 14.20'

9 Found 1/2" re-rod-Nail & Washer in 10" basswood S45°W 11.03'
 Nail & Washer in 12" Apple S05°E 13.19'
 Nail & Washer in Twin 12" basswood "E" 7.88'

16 Set 1/2" re-rod-Nail & Washer in P.P. S45°W 62.80'
 Nail in P.P. S25°E 47.79'
 C/L 4" Steel Fence Post N45°W 44.64'

SIGNED BY *George M. Young* DATE November 7, 1975

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

894 SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. ML 735
 DOUBLEDAY BROS. & CO., PALM BEACH, FLA.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
 DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 4 G 302

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 2 N. R. 1 E.	D-4 & E-4
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

AUG 25 8 30 AM '78

REGISTER OF DEEDS

Paula Johnson

INCHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

i. CHARLES F GARLOCK do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on SEPT 19, 1973 established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-4 FD. CORNER POST
 E-4 CORNER IN $\frac{1}{2}$ OF DITCH (NO ROAD FD. NO ROAD SET)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-4 COR POST
 EAST- 3' ± 6" MAPLE
 NORTH 7.5' ± $\frac{1}{2}$ WEST
 E-4 NOT ABLE TO WITNESS

SIGNED BY *Charles F. Garlock* DATE 8-23-78

SURVEYOR'S MICHIGAN REGISTRATION NO. 14762


FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



1296