

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 7 PAGE 305

FILED

For corners in

Ingham (County)	Located In:	Corner Code --#
1. Public Land Survey	T 3N R 1W	A-7
	T 3N R 1W	B-7
2. Property Controlling in Section	T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Nov 30 11 52 AM '92

REGISTER OF DEEDS  
*Dana Johnson*  
INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Alaiedon Township

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	13	14	15	16	17	18							
7													
8	19	20	21	22	23	24							
9													
10	25	26	27	28	29	30							
11													
12	31	32	33	34	35	36							
13													

I, Maurice H. Mahieu, in a field survey on September, 1991, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors (or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
A-7 Original Monument and Accessories were not found.

A-8 Original Monument and Accessories were not found.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-7 Found 1" Iron Rod in Monument Box in Intersection of College Road and Holt Road. Corner appears on MDOT Plans of US-127.

A-8 Found 1/2" Iron Rod in Monument Box in Holt Road. This corner was previously recorded by Fred White in Liber 1 of corners, Page 39 and is being re-recorded to update the witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7 1" Iron Rod in Monument Box, Witnessed By:  
Nail & Tag #28414 in West side Utility Pole N 30° E 60.40'  
Nail & Tag #28414 in North side Utility Pole N 80° E 47.65'  
Nail & Tag #18998 in East side Utility Pole S 70° W 87.20'  
Corner for Sec. 24, Delhi Township, South 25.10'

A-8 1/2" Iron Rod in Monument Box, Witnessed By:  
Nail & Tag #28414 in Northeast side of 28" Maple S 20" E 64.25'  
Nail & Tag #28414 in East side of 12" Ash S 00° W 42.15'  
Nail & Tag #18998 in East side of Utility Pole, N 15° W 43.40'  
Nail & Tag #28414 in West side Mail Box Post, N 25° E 27.77'



Signed by Maurice H Mahieu Date 11-30-92  
Surveyor's Michigan License No. 28414

*5/4 Cor. Sec 18 T34-R1W*

**LAND CORNER RECORDATION CERTIFICATE**  
**FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970**

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	<i>18 T. 3 N. R. 1 W.</i>	<i>7B</i>
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W.	
4. LOT NO. RECORDED PLAT		
5. PRIVATE CLAIMS		

LIBER **1 PG 39**

FILED

**JUL 13 4 25 PM '71**

REGISTER OF DEEDS  
*Mea Bill Humphrey*  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, *Fred N. White* do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on *July 14* 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and or subsequent restoration:
- B. Description of corner evidence found and or method applied in restoring or re-establishing corner:  
*Found pin over stone 4" deep in center of Holt Road*  
*14" Cherry S 05° W 42.67'*  
*16" Cherry S 70° W 88.90'*  
*8" Elm N 05° E 40.40'*  
*from MSHD notes by C.E. Smith Aug 30, 1963*
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
*Found 1/2" iron in Man. Box in center of Holt Road*  
*Power Pole N 20° W 44.40'*  
*Power Pole S 05° W 76.40'*  
*NW Cor. of building foundation S 20° E, 100.78'*

SIGNED BY *Fred N. White* DATE *July 13, 1971*

SURVEYOR'S MICHIGAN REGISTRATION NO. *12034*

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

*SW Cor. Sec. 18, T3N-R1W*

## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER **1 P 103**

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	<i>18 T. 3 N. R. 1 E.</i>	<i>7A</i>
2. PROPERTY CONTROLLING IN SECTION	T. N. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

FILED

**AUG 4 2 25 PM '71**

REGISTER OF DEEDS  
*Mia Bill Humphrey*  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, *Fred N. White* do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on *7-14* 19*71*, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

*3/4" pipe in center of College Road*  
*Tel. Pole S40°W 82.38*  
*Power Pole N25°E 57.75*  
*SW Cor. House N45°E 71.80'*  
*from MSHD notes by C.E. Smith Sept. 1963*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

*Found 3/4" pipe in mon. box in center of College Road & Holt Rd*  
*Tel. Pole S40°W 87.32'*  
*Power Pole N25°E 60.35'*  
*Power Pole N70°E 47.35'*

SIGNED BY *Fred N. White*  
 SURVEYOR'S MICHIGAN REGISTRATION NO. *12034*

DATE *7-16-71*

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PART-  
 APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR

DATE \_\_\_\_\_  
 (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

SW Cor. Sec. 18, T3N, R1W  
**LAND CORNER RECORDATION CERTIFICATE**  
 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 1 PG 217

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	18 T. 3 N. R. 1 W.	A-7
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W.	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

FILED  
 Nov 12 8 50 AM '71  
 REGISTER OF DEEDS  
*Mea Bill Humphrey*  
 INGHAM COUNTY, MICH.  
 REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Fred N. White do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on Sept 7 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19\_\_ found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

*Original Corner & Witnesses Obliterated*


B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

*3/4" Pipe in E College Rd & Holt Rd  
 found & verified from MSHD Records*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

*3/4" Pipe in mon box*

Tel. Pole	S 40° W	87.32'
Power Pole	N 25° E	60.35'
" "	N 70° E	47.35'



SIGNED BY Fred N. White DATE Nov. 11, 1971

SURVEYOR'S MICHIGAN REGISTRATION NO. 12034

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

*5 1/4 Cor. Sec. 18, T34, R1W*  
**LAND CORNER RECORDATION CERTIFICATE**

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 1 PG 219

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	<i>18</i> T. <i>3</i> N. R. <i>1</i> E.	<i>B-7</i>
2. PROPERTY CONTROLLING IN SECTION	T. N. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E.	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

**FILED**  
 Nov 12 8 50 AM '71  
 REGISTER OF DEEDS  
*Mia Bell Humphrey*  
 INGHAM COUNTY, MICH.  
 REGISTER OF DEEDS STAMP AND FILING NUMBER

I, *Fred N. White* do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on *Sept 7* 19*74*, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

*Original Corner & Witnesses Obliterated*

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

*1/2" iron rod in E Holt Rd.  
 found & verified from M.S.H.D. Records*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

*1/2" iron rod in mon. box*

<i>Power pole</i>	<i>S 05° W</i>	<i>76.40'</i>
<i>" "</i>	<i>N 20° W</i>	<i>48.40'</i>
<i>NW Cor. foundation</i>	<i>S 20° E</i>	<i>100.78'</i>

SIGNED BY *Fred N. White*  
 SURVEYOR'S MICHIGAN REGISTRATION NO. *12034*

DATE *Nov. 11, 1971*

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY  
 APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR

DATE \_\_\_\_\_  
 DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

Form No. MLM735  
 JOHNSON & CO., TOLAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
 DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

**LAND CORNER RECORDATION CERTIFICATE**  
**FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970**

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>Sec 20 T. 3 N. R. 1 E.</u>	<u>Alwipon Twp.</u>	<u>C-8, D-8</u>
2. PROPERTY CONTROLLING IN SECTION _____ T. _____ N. S. R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. S. R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

LIBER **1 R 633**  
 FILED  
 JUL 10 12 32 PM '72  
 REGISTER OF DEEDS  
*Carol M. Lewis*  
 INGHAM COUNTY, MICH.  
 REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Laverne J. Hendryx do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram-over) were, in a field survey on July 5 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:  
C-8 W 1/2 Post  
Painted Stone, 1" gas pipe beside

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-8 W 1/2 Post  
Painted Stone, 1" gas pipe beside  
4 ft. S. of Conc. Abut.  
2 Maple 24" S. 38.6  
2 Maple 24" SW 35.2  
2 Maple 12" NW 66.2  
D-8 Center Sec 20  
#4 Iron  
2 5" Ash W. 12.9  
2 12" Cherry NW 10.7  
2 8" Hawthorne SE 8.8  
1/2 LIMP 15 S. 1/2 of Road



SIGNED BY Laverne J. Hendryx DATE July 5, 1972

SURVEYOR'S MICHIGAN REGISTRATION NO. 3276

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY DATE \_\_\_\_\_  
 APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 4 PG 43

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 3N S. R. 1W W.	C-7, C-8
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

FILED

APR 29 3 29 PM '77

REGISTER OF DEEDS  
*Paula Johnson*  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, George M. Young do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on January 4, 1977 established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on January 4, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**A. Description of original monument and accessories and/or subsequent restoration:**

- C-7 Nail & Tag in S side 24" Walnut WNW 105.90'  
Nail & Tag in N side 30" Maple ESE 129.06'  
Nail & Tag in NE side 30" Maple SW 54.80'  
1" Bar in Mon. Box  
Recorded Liber 2, Page 149
- C-8 Tag in E side 36" Maple WNW 65.53'  
Tag in N side 40" Maple WSW 34.42'  
Tag in W side 36" Maple NNE 113.20'  
2" Iron Pipe Recorded Liber 2, Page 149

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

- C-7 Used Remaining accessories to locate corner.  
Found above said iron in Mon. Box.
- C-8 Used Remaining accessories to locate corner.  
Found above said pipe (bent over).

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

- C-7 Nail & Washer in 18" Walnut N 60° W 105.82'  
#16 Nail in T.P. N 45° W 61.21'  
#16 Nail in T.P. N 15° E 72.36'  
# 16 Nail in 36" Maple S 45° W 55.38'  
Found 3/4" Steel Rod in Monument Box
- C-8 Nail & Cap in 30" Maple N 25° E 113.10'  
#16 Nail in 36" Maple N 30° W 64.81'  
#16 Nail in 36" Maple S 80° W 34.72'  
Found 2" Iron Pipe (Bent Over)



SIGNED BY George M. Young DATE January 19, 1977

SURVEYOR'S MICHIGAN REGISTRATION NO. 17640 (SEAL)

FOR STATE AND UNITED STATES AGENCIES

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR DATE \_\_\_\_\_ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

INGHAM COUNTY  
**LAND CORNER RECORDATION CERTIFICATE**  
 FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

5 55

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 3 N. R. 1 E.	B-8
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED  
 Oct 25 1 33 PM '78  
 REGISTER OF DEEDS  
*Paula Johnson*  
 INGHAM COUNTY, MICH.  
 REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 5, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:  
 B-8 No record of corner being established in original government survey. County surveyors records show corner called for by T. J. Brown in a survey dated November 11, 1854. He states corner had been set by A. Jackson. No specific call for monument.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
 B-8 Center of Section 19, T3N, R1W  
 Set 1/2" bar and cap at intersection of old fences.  
 Measured North, 2678.27'; South, 2636.40'; East, 2652.58'; West, 3053.45'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
 B-8 1/2" bar and cap as described above  
 Nail & tag in East side 8" basswood, N.E., 25.78'  
 Nail & tag in N.E. side 18" maple, S.E., 24.38'  
 Nail & tag in North side 6" basswood, W.S.W., 17.09'  
 Nail & tag in East side 10" elm, North, 21.90'


SIGNED BY Ronnie M. Lester DATE 10/24/78

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_



SURVEYOR'S MICHIGAN REGISTRATION NO. 1442

1442

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 7 PAGE 305

FILED

For corners in

Ingham (County)	Located In:	Corner Code #
1. Public Land Survey	T 3N R 1W	A-7
	T 3N R 1W	B-7
2. Property Controlling in Section	T R	
	T R	
	T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Nov 30 11 52 AM '92

REGISTER OF DEEDS  
*Dana Johnson*  
INGHAM COUNTY, MICH.

Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

Alaiedon Township

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

I, Maurice H. Mahieu, in a field survey on September, 1991, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
  - A-7 Original Monument and Accessories were not found.
  - A-8 Original Monument and Accessories were not found.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - A-7 Found 1" Iron Rod in Monument Box in Intersection of College Road and Holt Road. Corner appears on MDOT Plans of US-127.
  - A-8 Found 1/2" Iron Rod in Monument Box in Holt Road. This corner was previously recorded by Fred White in Liber 1 of corners, Page 39 and is being re-recorded to update the witnesses.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - A-7 1" Iron Rod in Monument Box, Witnessed By:
    - Nail & Tag #28414 in West side Utility Pole N 30° E 60.40'
    - Nail & Tag #28414 in North side Utility Pole N 80° E 47.65'
    - Nail & Tag #18998 in East side Utility Pole S 70° W 87.20'
    - Corner for Sec. 24, Delhi Township, South 25.10'
  - A-8 1/2" Iron Rod in Monument Box, Witnessed By:
    - Nail & Tag #28414 in Northeast side of 28" Maple S 20° E 64.25'
    - Nail & Tag #28414 in East side of 12" Ash S 00° W 42.15'
    - Nail & Tag #18998 in East side of Utility Pole, N 15° W 44.40'
    - Nail & Tag #28414 in West side Mail Box Post, N 25° E 27.77'



Signed by Maurice H. Mahieu Date 11-30-92  
Surveyor's Michigan License No. 28414

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 22, 1971  
REVISED MAY 14, 1971  
REVISED JAN. 1981

2451