

SOURCE: G. L. O. FIELD NOTES P. 60
TRANSCRIBED from ~~ORIGINAL~~ on file at REMON OFFICE
DUPLICATE

60

North Between Sections 28 & 29

23.00 Be. 4 in diam.

25.00 Cut Trip

40.00 Set $\frac{1}{4}$ Sec post for a
Tourn. 8 in. S 73 @ 11 $\frac{1}{2}$ E-10
Do. 6.. N 47 W 8..

60.30 Maple 4" di.

80.00 Set post onto Sect. 20, 21, 28 & 29
Tourn. 3 in N 52 @ 18 W
Do. 4.. N 48 W 9..
Very bad Swamp. Timber. Tamarac.
Alder, Willow etc.

61

East On Random Between Sect. 21 & 28

40.00 Set a trip? $\frac{1}{4}$ Sec. post.

80.08 Set. N 4 S. line 12 lbs N. of post
All very bad Tamarac Swamp.

West Corrected Between Sect. 21 & 25.

40.04 Set $\frac{1}{4}$ Sec post at end. on the line
Tourn. 4 in. S 5 @ 25 W
Do 6.. N 34 W 14 "

40.81 Tourn. 3.. di.

80.08 To Sec Corner. Monday Jan. 1st 1827

Dec 29

SOURCE: G.L.O. FIELD NOTES

P. 71

TRANSCRIBED from ~~REMOVED~~ on file at REMON. OFFICE
DUPLICATE

71

North Between Sections 29 & 30.

19.23 Lyrus 14 in diam.
40.00 Set of 2 Sec. just from
Be 8 in N 226 19 lbs
Do. 18. S 5 W 18..
61.00 W. Oak 20 in di.
64.00 Ent: Willow Spruce

80.50 Set just cut's Sect 19, 20, 29 & 30 just
Maple 3 in. S 5 W 159 lbs.
Eln 8. S 6 E 100..

Sand Hilly and broken timbers
Oak. Bead v.v.v.

C-9

Dec 29
30

SOURCE: G. L. O. Field Notes P. 72
 TRANSCRIBED from ~~XXXXXX~~ DUPLICATE on file at REMON. OFFICE

| | |
|---|--|
| 72 | 73 |
| <p><u>East On Road on Between Sect 20 & 29</u></p> <p>6.60 At Brook 101. in Course N. 10°</p> <p>7.00 Left the Swamp</p> <p>36.00 Enter Do.</p> <p>40.00 Set a line 1/4 Sec. post.</p> <p>80.22 Set the N.W. 1/4 line 21 the South of the Post.</p> <p style="padding-left: 40px;">Land very Swampy & Bad.</p> <p><u>West Corridor Between Sect 20 & 29.</u></p> <p>40.11 Set 1/4 Sec. post for a</p> <p style="padding-left: 40px;">Willow 3 in. N 118 24 the</p> <p style="padding-left: 40px;">90° NEARLY</p> <p style="padding-left: 40px;">Do. 3 N 21 W 39</p> <p style="padding-left: 40px;">NEW BEARING TREE ELM 14 in. N 71 E</p> <p style="padding-left: 40px;">8 1/2</p> <p>47.10 Elm 6. di</p> <p>80.22 To See Corner</p> <p style="padding-left: 40px;">Thursday Jan. 4th 1827</p> | <p><u>North Between Sections 17 & 20.</u></p> <p>3.60 At Creek 101. in Course 10°</p> <p>4.50 Left the Swamp</p> <p>40.00 Set 1/4 Sec. post for a</p> <p style="padding-left: 40px;">Poc 10 in. N 59 E 32 the.</p> <p style="padding-left: 40px;">Do 10. N 53 W 9</p> <p>61.83 W. O. 24 in. di.</p> <p>66.00 Enter Tamarac Swamp</p> <p>79.00 Left the Sup.</p> <p>80.00 Set post Co. to Sect. 17, 18, 19 & 20 from</p> <p style="padding-left: 40px;">W. Ash. 10 in. N 27 E 15 the</p> <p style="padding-left: 40px;">Elm 12 in. S 33 1/2 W 50 1/4 the (near)</p> <p style="padding-left: 40px;">Row 4. N 57 W 18.</p> <p style="padding-left: 40px;">Land Hilly and Broken. Timber</p> <p style="padding-left: 40px;">Oak, Buck etc.</p> |

See 29

P. 347

DEEDS STAMP AND
NG NUMBER

Michigan P.A. of 1970,
1979, established,
nce with regulations
nent of the Interior,
ioned in lines 3, 4
ed or re-established
d Surveyors or, by a

er 24, 1826

854 (v.C. p.40).
r, December 7-9,

rch 18, 1874

to the north
.6' below
line to the
asured west

= crew.

= corner:

= concrete

72

DELT 1

East On Random Between Sect 20 & 29

6.60 at Break 10th. Corner 4th.

7.00 Left the Swamp

36.00 Enter Do.

40.00 Set a length 1/4 Sec post

80.22 Set the NW corner of the land of the 9th

Land very Swampy & Bad.

West Cornered Between Sect 20 & 29.

40.11 Set 1/4 Sec post for a

Willow 3 in. NW 1/4 24th May

GONE NEARLY

Do. 3 in. N 21 W 39"

NEW BEARING TREE ELY 1/4 NW 1/4 25

41.10 Elm 6. di

80.22 To the Corner

Thursday Jan. 4th 1827

73

North Between Sections 19 & 20.

7.60 at Break 10th. Corner 4th

14.00 Left the Swamp

40.00 Set 1/4 Sec. post for a

Do. 10 in. N 59 E 32th.

Do 10. N 53 W 9.

61.83 W. C. 2 in. di.

66.00 Enter Township Towners

79.00 Left the Swamp.

80.00 Set post Co. to Sect. 17. 18. 19 & 20 for a

W. Ark. Min. N 27 to 15th

from 12 in. 8 39% N 50% W 6 (W. C.)

from 4 in. N 57 W 18.

Land Hill and Broken. Timber

West. Bank etc.

sec 29