

INGHAM COUNTY - LANSING TWP.
LAND CORNER RECORDATION CERTIFICATE
 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 6 PG 39

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 4 N. S., R. 2 E. W.	J-4
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. S., R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

Mar 21 8 32 AM '80

REGISTER OF DEEDS

Paula Johnson

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on January 17, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- J-4 A. Description of original monument and accessories and/or subsequent restoration:
 No post set in original government survey.
 Corner identified as a stone in the private field notes of R.J. Robb, Co. Surveyor, date unknown. Calkins notes that in April 1911, he did not find any trace of the corner.
 Corner identified as a concrete monument with wood center in MDSHT Form 280, January 1965.
 Corner identified as a concrete monument in the records of the Ingham County Road Commission, revised grid map, 1972. Corner referred to in Recorded Subdivision Plats: Grand River Terrace Plat #1, 1954 (L.17, p.45-46); Kimberly Downs, 1960 (L.23, p.5-6); Brentwood, 1961 (L.23, p.36); Groesbeck Hills Subd. #9, 1963 (L.24, p.35); Kimberly Downs #1, 1963 (L.24, p.40); Kimberly Downs #2, 1963 (L.25, p.17); Kimberly Downs #5, 1968 (L.29, p.17).
- J-4 B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
 During investigation, found concrete monument with wooden center at the intersection of 4' high cyclone fences north, south, east and west, + 117.58' south of the south edge of Hopkins Street and + 169.80' west of west edge Kimberly Street. Accepted concrete monument with wooden center for corner as called for in MDSHT Form 280. Research conducted by Ingham County Survey and Remonumentation Project staff.
- J-4 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 Center, Section 11, T4N-R2W
 Found concrete monument with wooden center at location described above:
 MDSHT Nail & tag, west side power pole, NE, 1.13'
 Nail & tag, #18998, east side 8" Oak, SSW, 24.71'
 SE Corner of one story brick house #1244, Blake Street, SW, 133.00'
 SE Corner of one story brick and frame house #2724 and #2722, NNW, 49.81'

SIGNED BY Ronnie M. Lester



SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

~~FOR STAKE AND UNDEVELOPED STAKE OWNERS:~~

SIGNED BY _____

APPROVED AND SIGNED BY *Ronnie M. Lester*
 CHIEF OF SURVEY PARTY
 MICHIGAN REGISTERED LAND SURVEYOR
 Director, Ingham County Survey
 and Remonumentation Project

SURVEYOR'S MICHIGAN REGISTRATION NO. 17624



1790

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
 REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET