

INGHAM COUNTY  
**LAND CORNER RECORDATION CERTIFICATE**  
 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 2 PG 455

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>4</u>	T. <u>4</u> N. R. <u>2</u> E.	E-3, F-3
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. R. _____ E.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. R. _____ E.	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

FILED

JUN 28 1 25 PM '73  
 REGISTER OF DEEDS  
*Paul M. Linn*  
 INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie K. Lester do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on May 16, 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

E-3, Original monument and accessories obliterated.  
 F-3,

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-3, Set 1/2" bar in Centerline of Colby Rd. at prorated government measurement.  
 F-3, Set concrete nail in accord with KDSH records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3, SW Corner Section 4, T4N, R2E  
 1/2" bar Centerline Colby Rd.  
 Nail & Tag South side 2 1/2" tree, WNW, 213.40'  
 Nail & Tag South side 2 1/2" oak, ENE, 156.92'  
 SW corner brick house #3501, NE, 164.94'  
 F-3, S 1/4 Corner Section 4, T4N, R2E  
 Set concrete nail 8.32' East Centerline M-52 on front  
 Nail & Tag South side 20" hickory, ENE, 99.90'  
 Nail & Tag West side 36" oak, ESE, 115.28'


SIGNED BY Ronnie K. Lester DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

FOR STATE AND UNITED STATES AGENCIES:  
 SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_  
 FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
 DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS



INGHAM COUNTY-LOCKE TWP.

LAND CORNER RECORDATION CERTIFICATE  
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 4 N. R. 2 E.	D-3
2. PROPERTY CONTROLING IN SECTION	S. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION	S. R. E.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

LIBER 5 M 72

FILED

Nov 30 1 26 PM '78

REGISTER OF DEEDS  
*David Johnson*  
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Ronnie M. Lester, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Sept. 26, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law.

A. Description of original monument and accessories and/or subsequent restoration:

D-3  
Post set in original government survey by Joseph Wampler, March 29 to April 6, 1826.  
Corner referred to in subsequent survey by T.J. Brown, County Surveyor, dated Sept. 2, 1864 (v.3, p.15) and through a note added later by A.P. Drake, County Surveyor, dated May 28, 1879. No call for type of monument.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-3  
Excavated a 9' x 3' hole to an average depth of 3', ± 12' west of the intersection of the centerlines of Colby and Pringle Roads and on a fence/tree line to the west. Found an axle shaft surrounded by clay tile and supported by wood chips, on the extended centerline of Colby Road, ± 12' west of the centerline of Pringle Road and on the fence/tree line to the west. Measured ± 2630' east to E-3. Accepted axle shaft as corner.  
Excavation conducted by Ingham County Survey and Re-monumentation Project crew.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-3  
St Corner, Section 5, T4N-R2E  
Set 4" x 36" concrete monument with 1/2" x 38" rerod with cap #18998 at location of axle shaft described above:  
Placed small dent in west end C.M.P., South, 44.11'  
Nail & tag, #18998, south side 60' Walnut, NW, 129.01'  
Nail & tag, #18998, south side 5' Wood Fence Post, West, 16.69'  
Nail & tag, #18998, south side 24' Wild Cherry, West, 201.88'  
Found dent in north end C.M.P., East, 52.09'  
SE corner stone foundation of gray 2 story farmhouse, 1' above ground, East, 182.32'

SIGNED BY: Ronnie M. Lester DATE 11/29/78


SURVEYOR'S MICHIGAN REGISTRATION NO. 18998

SIGNED BY: Ronnie M. Lester DATE 11-29



Director, Ingham County Survey and Re-monumentation Project

REGISTRATION NO. 17624



FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
REVISED MAY 14, 1979

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

**LAND CORNER RECORDATION CERTIFICATE**

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Northeast Corner Section 7 Locke Twp.

LIBER 5 PG 283

FOR CORNER OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 4 N. R. 2 E.	G-3
2. PROPERTY CONTROLLING IN SECTION	T. N. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

FILED

AUG 27 3 45 PM '79

REGISTER OF DEEDS

*Paul Johnson*

INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, LARRY A. BRYAN, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 20, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

C-3 Post set in original Government Survey by Joseph Wampler, circa March-April, 1826.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-3 Found decayed anchor post surrounded by numerous 4"-8" diameter stones at the intersection of old fence lines East, West, and South. Accepted anchor post as corner location, measured South, East and West in close accord with G.L.O. distances.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-3 Northeast corner of Section 7, T4N, R2E  
 Set 1/2" iron bar with cap in center of decayed anchor post.  
 Set nail and tag, R.L.S. #25832, West side of 8" Ash, S30°E, 3.48'  
 Set nail and tag, R.L.S. #25832, West side of 22" Maple, N30°E, 30.54'  
 Set nail and tag, R.L.S. #25832, West side of 20" Maple, N50°E, 32.69'

SIGNED BY Larry A. Bryan

DATE August 24, 1979

SURVEYOR'S MICHIGAN REGISTRATION NO. 25832

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_

DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_

DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

1665



FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971  
 REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET