

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
SE. CORNER SECTION 5, T3N, R1E, WHEATFIELD TWP.
INGHAM COUNTY

LIBER 2 PG 355

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	3 N. R. 1 E	E-3
2. PROPERTY CONTROLLING IN SECTION	1 N. R. 1 E	
3. MISCELLANEOUS PROPERTY IN SECTION	1 N. R. 1 E	
4. LOT NO. RECORDED PLAT		
5. PRIVATE CLAIMS		

FILED

FEB 21 3 29 PM '73
REGISTER OF DEEDS
Ernie M. Lewis
INGHAM COUNTY, MICH

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, **James E. Stephens** do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on **December 26, 1972**, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on **1972**, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
The original monument and accessories were not found.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
A 1/2 inch iron pipe was found in the centerline of the two section line roads (Linn Road and Burkley Road).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
The 1/2 inch iron pipe found at the SE. corner was left in position with the following witnesses;

Survey tag in the S. side of a 36 inch Oak tree N28°39'W 56.55 feet.
Survey tag in the S. side of a 30 inch Oak tree N20°12'E 55.07 feet.
Survey tag in the W. side of a utility pole N50°41'E 41.97 feet.
The bearing of the section line west of the corner is assumed to be S89°14'19"W.

SIGNED BY *James E. Stephens*
SURVEYOR MICHIGAN REGISTRATION NO. 16053

DATE February 8, 1973


FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE

APPROVED AND SIGNED BY

DATE



SOURCE: CORNER RECORDATION CERTIFICATE

TRANSCRIBED from ORIGINAL on file at REGISTER OF DEEDS
~~DUPLICATE~~

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

LIBER 3 PG 77

FOR CORNERS OF -	LOCATED IN -	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	Sec 9 T. 3 N. R. 1 E.	P3 P4
2. PROPERTY CONTROLLING IN SECTION	N. S. R.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

FILED

APR 22 10 13 AM '74
REGISTER OF DEEDS
Paul M. Lewis
INGHAM COUNTY, MICH.

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Marvin F. Fouty do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on Jan. 22, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

P3 Original monument and accessories obliterated

P4 " " " "

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

P3 Found 1" iron pipe buried 6" in centerline of Ginn Rd. from MICH records and witnesses.

P4 Found concrete Anchor Post in median of Highway I-96 from MICH witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

P3 N 1/4 corner Section 9, T3N, R1E
1/2" bar with identification cap S02°29'32"E 33.01'
Nail & tag in W side 6" pine S5W 50.94'
Nail & tag in utility pole NW 48.16' FOUR PINE

P4 Center 1/4 Corner Section 9, T3N, R1E
Nail & tag S. side 14" beech W 43.14'
Nail & tag S side twin 10" beech E 12.03'
Nail & tag SE side 10" beech NE 32.67'

SIGNED BY Marvin F. Fouty DATE April 18, 1974

SURVEYOR'S MICHIGAN REGISTRATION NO. 18989

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



682

Form No. 55 (1973) REGISTER OF DEEDS & CO., GRAND RAPIDS, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

Center Sec 4 413 Wheatfield

413
9110

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LIBER 3 PG 563

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>Sec. 4</u>	T. <u>3N</u> S. <u>R.</u> E. <u>1E</u> W.	F2 G2 G3
2. PROPERTY CONTROLLING IN SECTION	T. _____ S. _____ R. _____ E. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ S. _____ R. _____ E. _____ W. _____	
4. LOT NO. _____	RECORDED PLAT _____	
5. PRIVATE CLAIMS _____		

FILED

Apr 28 1 59 PM '76

REGISTER OF DEEDS
Carl M. Lewis
INGHAM COUNTY, MICH.
REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Marvin F. Fouty, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 12-1, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____ found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and or subsequent restoration:
- F2 Center Corner not set in government survey. The center of Section was established by County Surveyor G. Edwin Stokes in April 1884.
 - G2 Original monument and accessories obliterated.
 - G3 Original monument and accessories obliterated.
- B. Description of corner evidence found and or method applied in restoring or re-establishing corner:
- F2 Center of Section occupied by anchor post at intersection of 1/4 line fences. Set 1/2" bar and cap at base of anchor post
 - G2 Found anchor post called for as E 1/4 corner by Surveyor F.N. White. Set 1/2" bar and cap at base of anchor post.
 - G3 Found 1/2" bar in Linn Road from witnesses furnished by Surveyor White.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F2 Center Sec. 4, T3N, R1E 1/2" bar and cap. G3 SE Cor. Sec. 4, T3N, R1E
Nail and Tag W. side 20" Oak N 5.48' 1/2" bar
Nail and Tag N. side 12" Poplar SW 18.58' Tag in Util. Pole NNW 26.92'
Nail and Tag E. side 12" Oak SSE 26.33' 4" steel Gate Post NE 28.5'
1 1/8" Square Iron N 33.00'
 - G2 E 1/4 Cor. Sec. 4, T3N, R1E 1/2" bar and cap
Nail and Tag NE side 18" Maple S 14.89'
Nail and Tag N. side 12" Poplar E 33.88'
Nail and Tag E. side 18" Tw. Map. NW 43.05'


SIGNED BY *Marvin Fouty* DATE April 26, 1976

SURVEYOR'S MICHIGAN REGISTRATION NO. 18989

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Center Sec 4 4/3 Wheatfield
 4/3
 9/10

LAND CORNER RECORDATION CERTIFICATE
 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY Sec. 3N S. R. 1E T. 4		F2 G2 G3
2. PROPERTY CONTROLLING IN SECTION T S. R. E		
3. MISCELLANEOUS PROPERTY IN SECTION T S. R. E		
4. LOT NO. RECORDED PLAT		
5. PRIVATE CLAIMS		

LIBER 3 PG 563

FILED

APR 28 1 59 PM '76

REGISTER OF DEEDS
 Carol M. Lewis
 INGHAM COUNTY, MICH.
 REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Marvin F. Fouty, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 12-1, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and or subsequent restoration:
- F2 Center Corner not set in government survey. The center of Section was established by County Surveyor G. Edwin Stokes in April 1884.
 - G2 Original monument and accessories obliterated.
 - G3 Original monument and accessories obliterated.
- B. Description of corner evidence found and or method applied in restoring or re-establishing corner:
- F2 Center of Section occupied by anchor post at intersection of 1/4 line fences. Set 1/2" bar and cap at base of anchor post
 - G2 Found anchor post called for as E 1/4 corner by Surveyor F.N. White. Set 1/2" bar and cap at base of anchor post.
 - G3 Found 1/2" bar in Linn Road from witnesses furnished by Surveyor White.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F2 Center Sec. 4, T3N, R1E 1/2" bar and cap. G3 SE Cor. Sec. 4, T3N, R1E
 Nail and Tag W. side 20" Oak N 5.48' 1/2" bar
 Nail and Tag N. side 12" Poplar SW 18.58' Tag in Util. Pole NNW 26.92'
 Nail and Tag E. side 12" Oak SE 26.33' 4" steel Gate Post NE 28.5'
 1 1/8" Square Iron N 33.00'
 - G2 E 1/4 Cor. Sec. 4, T3N, R1E 1/2" bar and cap
 Nail and Tag NE side 18" Maple S 14.89'
 Nail and Tag N. side 12" Poplar E 33.88'
 Nail and Tag E. side 18" Tw. Map. NW 43.05'

SIGNED BY Marvin Fouty DATE April 26, 1976
 SURVEYOR'S MICHIGAN REGISTRATION NO. 18989
 FOR STATE AND UNITED STATES AGENCIES:
 SIGNED BY _____ DATE _____
 APPROVED AND SIGNED BY _____ DATE _____
 SURVEYOR'S MICHIGAN REGISTRATION NO. _____



LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
PRE-APPROVED
W 1/2 Post Section 4 T34N, R1E, W1/2pt 11d

LIBER 4 PG

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>4</u> T. <u>3</u> N. R. <u>1</u> E.		<u>E-2</u>
2. PROPERTY CONTROLLING IN SECTION _____ T. _____ S. R. _____ W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ S. R. _____ W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

FILED

SEP 16 10 40 AM
 REGISTER OF DEEDS
Paula Johnson
 INCHAM COUNTY, M

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Laverne J. Hendryx, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above were, in a field survey on July 6, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by Decree of a Court of law:

A. Description of original monument and accessories and or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
Gas pipe E 33.0

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E & Iron
Gas pipe E. 33.0
Center of 7" Oak N N W 43'10"
Center of 4" Hickory SE 32'3"

SIGNED BY Laverne J. Hendryx DATE July 6, 1976

SURVEYOR'S MICHIGAN REGISTRATION NO. 3276

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

